



Outstanding performance in tapping high hardness steels over 50HRC.

(WIN

Mold and Die industry




The mold industry is roughly divided into mold die (Mold) and metal press die (Die) used for casting and resin molding.

Materials used in mold dies are often stainless steel-based materials with excellent corrosion resistance and mold materials of about 40HRC.

In the threading process, mold materials which exceed 50HRC can not be processed with a tap made of HSS. It is necessary to tap with a HSS tap before heat treatment. However, in the case where the pre-hardned material that has been heat-treated Yamawa has developed our UH-CT series of tools.

The UH-CT reduces cycle times and increases productivity.

YAMAWA Carbide Taps for hard materials, UH-CT



Chamfer length is 5P for better tool life.

Coating

Special coating improves heat resistance and wear resistance.

YAMAWA

Material

It is produced from a ultra fine grain cemented carbide with superior abrasion resistance and impact resistance.

Shank


The UH-CT has an improved shank roundness accuracy.

Special cutting angle



Avoid chipping by adopting special cutting angle.

Flute design




Compared with general purpose taps, increased number of flutes and adopted special flute shape for improving wear resistance and smooth chip ejection.





Special chamfer design of UH-CT Tap




The end diameter of UH-CT is designed to be larger than that of general purpose taps according to the maximum value of 6H intrenal threads.

We recommend to make bored hole before tapping as close as maximum figure of 6H internal thread. If you make small hole size, it will be caused for chipping at the chamfer or tap breakage of cutting edge.

Recommended bored hole size before tapping

| | Recommended | Minor. dia. | | | |
|----------|-----------------------------------|-------------|--------|--|--|
| Size | bored hole size before tapping | Max. | Min. | | |
| M3X0.5 | 2.55 | 2.599 | 2.459 | | |
| M4X0.7 | 3.4 | 3.422 | 3.242 | | |
| M5X0.8 | 4.3 | 4.334 | 4.134 | | |
| M6X1 | 5.1 | 5.153 | 4.917 | | |
| M8X1.25 | 6.9 | 6.912 | 6.647 | | |
| M10X1.5 | 8.6 | 8.676 | 8.376 | | |
| M12X1.75 | 10.4 | 10.441 | 10.106 | | |
| M14X2 | 12.2 | 12.210 | 11.835 | | |
| M16X2 | 14.2 | 14.210 | 13.835 | | |
| M18X2.5 | 15.7 | 15.744 | 15.294 | | |
| M20X2.5 | 17.7 | 17.744 | 17.294 | | |




For example M8X1.25, by adjusting bored hole from 6.8mm to 6.9mm, the volume of chips will decrease by 15%. Also, tapping load decreases as well by 13%.

Larger bored holes can decrease tap breakage and chipping problems.

Precautions of Processing

- ① Make the bored hole as large as possible within an allowable range and work. If the bored hole is made larger, the processing load is reduced, so more stable stapping becomes possible.
- 2) Pay attension to vibration while tapping, tap bending, tapping speed and process it.
- ③ Make the depth of the prepared hole before tapping as deep as possible within an allowable range.
 If the tap cuts the chips that accumulated the bottom of the bored holes, this will create a flute chipping problem.

If it is not possible to deepen the bored hole, we suggest that once you have tapped about half of the thread length, remove the tap once, remove the chips and continue tapping to the bottom of the hole.







Recommended tapping condition

| Type of material | Hardness | Recommended tapping speed (m/min) | | | |
|-----------------------------|----------|---|--|--|--|
| Hot forging die | 50~55HRC | 2~6 | | | |
| Cold forging die (SKD11) | 56~63HRC | 1~4 | | | |

<Recommended tapping length>
Major diameter X1.5 or less



Chips ejected by UH-CT


Tapping record

UH-CT can continue to be used without any chipping or breakage. Parted small chips eject because of the special cutting angle.


| Size | Material (HRC) | Bored hole size (mm) | Machine | Tapping speed (m/min) | Feed | Lubrication | Number of tapped hole (hole/pc) |
|----------|---------------------------|----------------------------|---------|-----------------------------|--------------|-------------------|---------------------------------------|
| M6X1 | SKD11 (60HRC) | 5.1 | M/C | 3 | | Non-soluble oil | 100 |
| M8X1.25 | SKD11 (58HRC) | 6.9 | M/C | 1.5 | Synchronized | Water soluble oil | 80 |
| M8X1.25 | Hardened steel (60HRC) | 6.9 | M/C | 2.5 | Synchronized | Water soluble oil | 60 |
| M12X1.75 | SKD11 (58HRC) | 10.4 | CNC | 2 | | Non-soluble oil | 30 |

Dimensions and Sizes
















| Size | Code | L _(mm) | L (mm) | Ds (mm) | K _(mm) | ℓk (mm) | No. of flutes | TYPE | Chamfer length | Recommended bored hole size |
|----------|-------------|-------------------|---------------|------------|-------------------|------------|---------------|------|-------------------|-----------------------------------|
| M3X0.5 | TD3.0GBBWA5 | 56 | 11 | 3.5 | 2.7 | 6 | 4 | 1 | | 2.55 |
| M4X0.7 | TD4.0IBBWA5 | 63 | 13 | 4.5 | 3.4 | 6 | 4 | 1 | | 3.4 |
| M5X0.8 | TD5.0KBBWA5 | 70 | 16 | 6 | 4.9 | 8 | 4 | 1 | | 4.3 |
| M6X1 | TD6.0MBBWA5 | 80 | 19 | 6 | 4.9 | 8 | 5 | 1 | | 5.1 |
| M8X1.25 | TD8.0NBBWA5 | 90 | 22 | 8 | 6.2 | 9 | 5 | 2 | | 6.9 |
| M10X1.5 | TD010OBBWA5 | 100 | 24 | 10 | 8 | 11 | 5 | 2 | 5P | 8.6 |
| M12X1.75 | TG012PBBWA5 | 110 | 29 | 9 | 7 | 10 | 5 | 3 | | 10.4 |
| M14X2 | TG014QBBWA5 | 110 | 30 | 11 | 9 | 12 | 6 | 3 | | 12.2 |
| M16X2 | TG016QBBWA5 | 110 | 32 | 12 | 9 | 12 | 6 | 3 | | 14.2 |
| M18X2.5 | TG018RBBWA5 | 125 | 34 | 14 | 11 | 14 | 6 | 3 | | 15.7 |
| M20X2.5 | TG020RBBWA5 | 140 | 34 | 16 | 12 | 15 | 6 | 3 | | 17.7 |

Warning

- ◆Tools may shatter. Wear cover or eye glasses to avoid injury during tapping.
- ◆Tools may shatter. Use tools under the proper tapping condition.
- ♦Never wear gloves during turning operations as the gloves may get caught with the tools.
- ♦Wear safety shoes to avoid injuring yourself by the falling tools.
- ♦On attaching tools to the machine, fasten firmly to avoid chattering and run-out.
- ◆Fasten the work pieces firmly so that they never move during operation. Never use worn tools or damaged tools with chipping.
- ◆Take a special care to fire trouble. High temperature during machining may cause fire.



